



JON M. HUNTSMAN, JR.
Governor
GARY R. HERBERT
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report
Minerals Regulatory Program
Date: March 15, 2009

Reviewed: PPB

Mine Name: Poverty Point	Permit Number: M/045/0012
Operator Name: Holcim (US) Inc	Inspection Date: 10-29-2008
Inspector(s): L Heppler	Time: 3:00 PM
Other Participants: none	Mine Status: ACT

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts,	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Bond Renewal Date: 04-29-2010 **Bond Amount:** \$151,800 **Permit fee** is up to date

Purpose of Inspection: Routine annual inspection

Inspection Summary: No mining equipment on site, one fuel storage tank on site. Disturbance is limited to GIS foot print in the DOGM file.

Photos were taken to document site conditions.

Conclusions and Recommendations: Leaky tank needs to be removed. OGM discussed the removal of the tank with operator immediately after inspection. OGM to continue annual inspections and monitor the site when in the area.

Inspector's Signature

LAH:vs

cc: Ken George

SITLA - Jblake@utah.gov

O:\M045-Tooele\M0450012-PovertyPoint\inspections\insp_10292008.doc



Close up view of Fuel Tank



View looking south from the top of the mine



Panoramic view of the pit



Panoramic view of the pit